



The Professional Esprit Windscreen Chip & Crack Repair System





Esprit specialises in Windscreen repair systems and have over 35 years experience as a manufacturer



The Esprit Repair System is suitable for all types of repairs.

STAR CHIPS





The Esprit Elite Kit Contains Everything You Need.



Using the Esprit Resin and Repair Kit together,



Repairs are approved to Australian Standard

> AS/NZS 2366.2-1999

T

Self Levelling Bridge



240V Power Adaptor



One Universal Repair Resin



Quality 12V Drill



75 Second 12V LED UV Curing Lamp



Swivelling Inspection Mirror







Advantages of the Esprit System

- The system used by leading windscreen repairers worldwide
- Supported and stocked nationally by ALP OZ / BTB Tools.
- Simple, fast, accurate, step-by-step setup.
- One quality UV repair resin for all windscreen repairs.
- $\bullet\,$ Best quality, best value, don't settle for inferior copies.
- Designed for Leading Mobile Technicians.
- Approved to Australian Standard AS/NZS 2366.2–1999.
- The repair restores strength and optical clarity of the glass.
- 35 years development behind the Elite Repair Bridge.
- · No risk of yellowing.
- Training DVD and Manual provided.

HALLAM BRANCH t. 03 9703 1522 alpoz.com.au e. sales@alpoz.com.au







Esprit Kits

alpoz.com.au/videos

KIT CONTENTS:

- ♣ Elite Repair Bridge♣ Proxxon Drill
- CLED UV Curing Lamp
- O Heater Unit
- 240V / 12V Adaptor
- O Professional Aluminium Case
- ☼ Elite Inspection Mirror❖ 4 x Resin Packs
- Pit Fill Resin
- Pit Fill Polish
- Stop Crack Punch Water Based Gel
- 2 x 1.6mm Drill Burs
- 3 x 1.0mm Drill Burs
- 🗘 Countdown timer
- Razor Blades
- Green LED Inspection Torch
- UV Curing Film
- Cleaning Probe
- UV Shield
 Training DVD & Manual

ENOUGH RESIN FOR 40 REPAIRS



LEDCOMPELITE Esprit LED Compact Elite Windscreen Repair Kit



KIT CONTENTS: © Elite Repair Bridge © Glass Drill ☼ LED UV Lamp ❖ Plastic Carry Case ❖ Elite Inspection Mirror 🗘 2 x Resin Packs 🗘 Pit Fill Resin 🗘 Pit Fill Polish Stop Crack Punch © Water Based Gel © 2 x 1.6mm Drill Burs © 3 x 1.0mm Drill Burs © Razor Blades © UV Curing Film © Cleaning Probe © UV Shield © Training

Quality Esprit System Spares and Consumables







3m extension lead included



ESMB150 Esprit Glass Repair Drill (Black) - 12V



3m extension lead included





3m extension lead included

ESELBR Esprit Elite Pro Repair **Bridge**



🗘 Fast to set-up self-levelling bridge C Light weight & robust

DVHEAT12 Esprit Heater/ Moisture Evaporator - 12V

O Professionally warm the glass to a controlled temperature before repairing Oldeal for drying moisture



ESPSU-AU Esprit Spare - 240 **Volt Wall Power Adaptor**



continuous library lib





DVCPL Esprit Cig Ext Cable 3Mtr - Male - Single Pin



ESINJSSPK Esprit Stainless Steel

O Designed to be used again and again with the Esprit bridge



O NEW O

Injector and 2ml Resin Pack

3 year warranty

BENDIGO BRANCH t. 03 5443 1755 alpoz.com.au e. sales@alpoz.com.au







Quality Esprit System Spares and Consumables cont...





































Bonnet Protectors













Oz Windscreen Repair Kits & Consumables



- Aluminium Bridge Milwaukee Cordless Drill (Drill charger not
- included) Cordless UV light
- ♣ Repair Resin
 ♠ Pit Fill Resin
- O Nitrile Gloves
- Mylar Film
- O Probe
- Syringe & Needles
- Seal Kits
- O Drill Bits



NEW DESIGN

PL-400P Oz Pro Windscreen Repair Kit

Everything contained in the #PL-400 Kit

- An extra Bridge
- C Extra resins
- Spot mirror (Drill charger not included)



PL-204 Oz Windscreen Repair **Bridge**



M18-30 Milwaukee M12-M18 **Battery Charger**







O Variable speed trigger

🖨 Equalizer.



O Durable C Fully adjustable with a telescopic lens and mounting bracket

🗘 Small O Powerful

O NEW O





O NEW O









O NEW O

PL-214 OZ Windscreen Repair Seal Kit 0-Rings - Pkt 20

with Mounting Bracket





PL-102 Oz 15ml Repair Resin - THIN

🗘 10 to 15 repairs



PL-103 Oz 15ml Repair Resin



PL-106 Oz 15ml Pit Fill Resin - HARD FINISHING



PL-119-PK5 Oz Windscreen Repair Drill Bits - Pkt 5



PL-205 Oz Repair Probe



PL-123 Oz Spot Inspection



PL-125 Oz Mylar UV Curing Patches - Pkt 10

